

CERTIFICATE OF COMPLIANCE

Certificate Number E165879
Report Reference E165879-20120828
Issue Date 2020-JUNE-09

Issued to: SYSTEMAIR MFG INC
10048 INDUSTRIAL BLVD
LENEXA KS 66215

**This certificate confirms that
representative samples of**

DRYER-EXHAUST-DUCT POWER VENTILATORS
Model: DBF4XLT-705, DEDPV-705 and DPV22-2

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 705, Power Ventilators
CSA C22.2 No. 113-18, Fans and Ventilators

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

